

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-006345**Date Inspected:** 12-Apr-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Shi Lei**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segments**Summary of Items Observed:**

On this date CALTRANS OSM Quality Assurance (QA) Inspector Dan Hernandez was present during the times noted above for observations relative to the work being performed.

On this date Caltrans OSM Quality Assurance (QA) Inspector, Dan Hernandez was present during the times noted above to observe the fit up, welding and related activities associated with the fabrication of the San Francisco Oakland Bay Self Anchored Suspension Bridge at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

OBG Assembly

Segment 2AW

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SEG007E-073, 070, 097, 100. The welder is identified #067656 and was observed welding in the 3G (vertical) position.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Fillet weld joint. The Weld joint is designated as SEG007E-098, 099, 134, 135. The welder is identified #067942 and was observed welding in the 4F (overhead) position.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

(CJP) weld joint. The Weld joint is designated as SEG007E-145, 106, 172. The welder is identified #058087 and was observed welding in the 3G (vertical) position.

Segment 1BW

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SSD46A-PP11-253. The welder is identified #066258 and was observed welding in the 4G (overhead) position.

Segment 7DE

This QA Inspector observed Shielded Metal Arc Welding (SMAW) tack welding. The Weld joint is designated as SEG040-006. The welder is identified #215993 and was observed welding in the 1G (flat) position.

Segment 7EE

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SEG042-004. The welder is identified #048038 and was observed welding the root pass in the 1G (flat) position.

Segment 76CE

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as CA030-004. The welder is identified #051356 and was observed welding in the 1G (flat) position.

An electrode storage oven was observed being used during welding operations.

ZPMC Quality Control (QC) Inspector is identified as Geng Wei. QA Inspector observed QC Inspector verify welding parameters. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372 , who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By: Hernandez,Dan

Quality Assurance Inspector

Reviewed By: Carreon,Albert

QA Reviewer